



# **Retrofit Dowel Bars In Jointed Concrete Pavement - Long Term Performance and Best Practices**

Tom Burnham, P.E.

Bernard Izevbekhai, P.E.

Office of Materials and Road Research  
Minnesota Department of Transportation

**NATIONAL CONFERENCE ON PRESERVATION, REPAIR, AND  
REHABILITATION OF CONCRETE PAVEMENTS**

**St. Louis, Missouri – April 21-24, 2009**

# Outline

- Background
- Long Term Performance Case Studies
- Minnesota Best Practices
- Construction Issues and Rehabilitation

# Background

- One of the major distresses in jointed concrete pavement is joint and or crack faulting
  - Traffic load/volume change (previously undoweled)
  - Excessive panel length (mid-panel cracks)
  - Dowel deterioration (not common)
- Retrofit dowel bars are a proven technique
  - Most research focused on quantity and spacing of bars
- Need to understand longer term performance with respect to backfill material in extreme climates

# Long Term Performance Case Studies

## *TH 52, Zumbrota, Minnesota*

- First retrofit dowel bar project in state - 1994
- Original 9" thick JRCF pavement constructed in 1984
  - 27 foot long panels, mesh reinforcement across mid-panel cracks
  - Virtually no faulting of mid-panel cracks (10 years old)
  - Transverse doweled contraction joints in good condition
  - HCADT = Approx 2100
- Project objective: To determine if retrofit dowel bars could prevent or slow down faulting of mid-panel cracks
  - No surface grinding necessary (no faulting yet)


# Long Term Performance Case Studies

## *TH 52, Zumbrota, Minnesota*

- Design variables
  - Backfill mortar type
    - Polymer-modified quickset patch (PMQP) material
    - Mn/DOT 3U18 patch mix
  - Saw and chip slotting method
  - Two dowel bar sizes
    - 1.5 inch dia. x 15 inch long
    - 1.5 inch dia. x 18 inch long
  - Various retrofit dowel bar placement patterns

# Long Term Performance Case Studies

## *TH 52, Zumbrota, Minnesota*



# Long Term Performance Case Studies

## *TH 52, Zumbrota, Minnesota*

- Observed Performance (14 years after retrofit)
  - Faulting of mid-panel cracks minimal (avg = 1.7 mm)
  - Small number of distressed retrofit dowel bar slots caused by longitudinal cracking
  - Backfill material performance very good
    - PMQP had some loss of material near surface
    - Mn/DOT 3U18 patch mix good despite early shrinkage cracking around slots
  - LTE (2006)
    - 60 to 80 percent

# Long Term Performance Case Studies

*TH 52, Zumbrota, Minnesota*

*13 years old*



Longitudinal panel crack



# Long Term Performance Case Studies

*TH 52, Zumbrota, Minnesota*

*13 years old*



Mn/DOT 3U18



PMPQ

# Long Term Performance Case Studies

*TH 52, Zumbrota, Minnesota*

*13 years old*



Faulted mid-panel crack

# Long Term Performance Case Studies

## *TH 12, Willmar, Minnesota*

- Retrofit in 1996
- Original 8” thick JPCP pavement constructed in 1981
  - 15 foot long panels, undoweled transverse joints
  - Substantial faulting in outside wheel tracks (15 years old)
  - Wide joint openings (up to 1.25 inch)
  - HCADT = Approx 600
- Project objective: To determine if retrofit dowel bars and surface grinding could extend service life


# Long Term Performance Case Studies

## *TH 12, Willmar, Minnesota*

- Design variables
  - Backfill mortar type
    - Mn/DOT 3U18 patch mix
  - Slots established using milling machine
  - Dowel bar size
    - 1.5 inch dia. x 18 inch long
  - Two retrofit dowel bar placement patterns

# Long Term Performance Case Studies

## *TH 12, Willmar, Minnesota*



# Long Term Performance Case Studies

## *TH 12, Willmar, Minnesota*

- Observed Performance (12 years after retrofit)
  - Faulting of transverse joints minimal (avg = 1.5 mm)
  - Backfill material performance good
    - Minor surface distress in slots near joint
    - May be linked to milling process
  - LTE (2006)
    - 51 to 65 percent

# Long Term Performance Case Studies

*TH 12, Willmar, Minnesota*

*12 years old*



Backfill mortar distress near joint

# Long Term Performance Case Studies

## *TH 23, Mora, Minnesota*

- Retrofit in 1998
- Original 9-7-9” thick JPCP pavement constructed in 1952
  - 16 foot long panels, undoweled transverse joints
  - Substantial faulting in outside wheel tracks (46 years old)
  - Wide joint openings (no aggregate interlock)
  - HCADT = Approx 500
- Project objective: To determine if retrofit dowel bars and surface grinding could extend service life of a very old pavement




# Long Term Performance Case Studies

## *TH 23, Mora, Minnesota*

- Design variables
  - Backfill mortar types
    - Rapid Set Mortar (RSM)
    - Mn/DOT 3U18 patch mix
  - Saw and chip slotting method
  - Two dowel bar size
    - 1.5 inch dia. x 15 inch long
    - 1.5 inch dia. x 13 inch long
  - Various retrofit dowel bar placement patterns

# Long Term Performance Case Studies

## *TH 23, Mora, Minnesota*



# Long Term Performance Case Studies

## *TH 23, Mora, Minnesota*

- Observed Performance (10 years after retrofit)
  - Faulting of transverse joints minimal (avg = 0.5 mm)
  - Backfill material performance very good
  - LTE (2006)
    - 64 to 80 percent

# Long Term Performance Case Studies

*TH 23, Mora, Minnesota*

*8 years old*



Mn/DOT 3U18 backfill mortar

# Long Term Performance Case Studies

## *I-90, Beaver Creek, Minnesota*

- Retrofit in 1999
- Original 9” thick JRCF pavement constructed in 1984
  - 27 foot long panels, mesh reinforcement across mid-panel cracks
  - Significant faulting of mid-panel cracks (15 years old)
  - Transverse doweled contraction joints in good condition
  - HCADT = Approx 1200
- Project objective: To determine if retrofit dowel bars and surface grinding could restore ride quality and slow down redevelopment of mid-panel crack faulting


# Long Term Performance Case Studies

## *I-90, Beaver Creek, Minnesota*

- Design variables
  - Backfill mortar type
    - PMPQ patch mix
  - Saw and chip slotting method
  - Dowel bar size
    - 1.5 inch dia. x 15 inch long
  - Two retrofit dowel bar placement patterns

# Long Term Performance Case Studies

## *I-90, Beaver Creek, Minnesota*



# Long Term Performance Case Studies

## *I-90, Beaver Creek, Minnesota*

- Observed Performance (9 years after retrofit)
  - Faulting of mid-panel cracks minimal (avg = 0.3 mm)
  - Backfill material performance very good
  - Some slot distresses caused by transverse and longitudinal panel cracking after retrofit installation
  - LTE (2006)
    - 70 to 89 percent



# Long Term Performance Case Studies

- **Summary**
  - Retrofit dowel bar applications:
    - Prevention of faulted mid-panel cracks
    - Structural capacity improvement
    - Extension of service life (for very old pavement)
    - Restoration of ride quality

# Long Term Performance Case Studies

- **Conclusions**

- Effective in preventing faulting of mid-panel cracks
- Effective in extending service life of previously undoweled joints
- Surface grinding critical to performance of retrofit dowel bars
- Fairly insensitive to various dowel patterns and bar length
- Good performance from most backfill materials
- Milling not recommended for slot formation

# Minnesota Best Practices

- **Development issues**
  - Economical construction
  - Long-term durability in extreme climate
- **Slot formation**
  - Saw and Chip recommended
  - Milling quicker, but long-term performance not as good
- **Dowel bar length**
  - 1.25 inch dia x 15 inch long recommended
  - Minne-ALF testing demonstrated that bar lengths down to 13 inches perform satisfactorily (= shorter slots)


# Minnesota Best Practices

- Dowel bar placement
  - Faulting near outer wheelpath  
= 3 dowels outer wheel track
  - Faulting across entire joint/crack  
= 3 dowels outer wheel track, 2 dowels inside wheel track
  - Adjust for traffic volume (example: passing lane)  
= 2 dowels outer wheel track, 2 dowels inside wheel track
  - Center groups of bars within wheel track (12 inches on center)
  - Install so embedment length is equal across joint or mid-panel crack

Note: Two dowels in a wheel track are as efficient as three, however joint deflections increase (Minne-ALF results)

# Minnesota Best Practices

- Dowel bar design



Shallower cover has been found to work successfully (Minne-ALF)

# Minnesota Best Practices



# Minnesota Best Practices

- Construction Method
  - Mn/DOT requires contractor to construct a small test section
    - 24 retrofit dowels in test area
    - 24 hours after retrofit installation, three 6 inch diameter cores taken and inspected
      - Continuity at dowel/concrete interface and consolidation beneath dowel
      - Check that dowel supports do not collapse
      - Check bond between backfill mortar and slab
    - Paid for at unit price


# Construction Issues



Honeycombing of backfill mortar ► Switched mortar type




# Rehabilitation of Retrofit



Age = Approximately 5years

# Rehabilitation of Retrofit



Age = Approximately 5years



# Thank you



# QUESTIONS?