

**STATUS OF DRINKING WATER OUTLETS EXCEEDING THE STATE LEVEL OF 15 PARTS/BILLION (PPB)**

<b>Building</b>	<b>Sample Number</b>	<b>Location</b>	<b>Test Results (PPB)</b>	<b>Outlet Type</b>	<b>Action Taken</b>
<b>Aymer J. Hamilton</b>	AJH-WW-001A	Covered walkway near Women's Restroom	15.4	Water Fountain	Removed from service, replaced, and retested. ** Retest results met standard.
	AJH-102-001	Room 102A	23.4	Hand Washing Sink	Posted "Hand washing only".
	AJH-108-003	Room 108F	62.5	Lab Sink	Posted "Do not drink".
	AJH-108-002	Room 108E	17.9	Lab Sink	Posted "Do not drink".
	AJH-108-004	Room 108J	25.5	Lab Sink	Posted "Do not drink".
<b>Lassen Hall</b>	LASS-3MB-002	3rd Floor Men's Restroom	26.0	Sink	Replaced and retested. **Retest results met standard.
	LASS-1MB-002	1st Floor Men's Restroom	23.6	Sink	Replaced and retested. **Retest results met standard.
<b>Physcial Science Bldg</b>	PHY-218-001	Room 218	59.7	Sink	Replaced and retested. **Retest results met standard.
<b>Student Health Center</b>	SHC-HW-240-001	Hallway	30.3	Sink	Exam room being used as an office. Posted "Do not drink".
<b>Yolo Hall</b>	YOLO-HW-244-002	Hallway	16.4	Water Fountain (high)	Water supply interrupted during sampling. Removed from service and retested. ** Retest results met standard. Returned to service.
<b>University Village</b>	UV-BLDG10-188	Room 188	29.2	Sink	Replaced. Retesting conducted. ** Retest results met standard.
	UV-BLDG10-K02B	Kitchen	15.9	Sink	Replaced. Retesting conducted. ** Retest results met standard.
<b>University Farm</b>	ARTC-321-102KS	Kitchen Sink	30.2	Sink	Removed from Service. Retest results met standard.